

TMA can offer a **COMPLETE INSPECTION SERVICE** for power press users in line with HSG 236 guidance.

A TMA service engineer can travel to your factory, strip your press to expose the safety critical components and carry out an NDT inspection on all the relevant parts, then re-assemble the press (if all components are ok) and issue a full HSG 236 Inspection Report.


TMA service engineers are qualified to **PCN Level 2 NDT** using the Magnetic Particle Method which is recognised by the British Institute of Non-Destructive Testing (BINDT).

The HSG 236 Inspection Report can be given to your insurance company as evidence the NDT inspection has been carried out by a certified engineer eliminating the need for your inspector to attend site, saving you money.

Please do not hesitate to contact us if you require any further information or a quote.



We can also provide a full **HSG236 Electrical Inspection** if required.



NEW POWER PRESSES
NEW TMA SERVO FEEDS
NEW COIL FEED EQUIPMENT

*for **ALL** your **POWER PRESS** requirements*